

## **Change Order 1**

### The Restore Louisiana Homeowner Assistance Program

 Insured:
 Pearline Foley
 Cell:
 (504) 259-7927

 Home:
 6 Princeton Pl
 Home:
 (504) 259-7928

Kenner, LA 70065 Other: (504) 439-4270

E-mail: vfoley001@yahoo.com

Claim Rep.: Chris Swider Business: (985) 502-1893

Estimator: Chris Swider Business: (985) 502-1893

Reference:

Company: Single Family Home

Claim Number: 282522 Policy Number: 282522 Type of Loss: Hurricane

Date Contacted: 10/9/2023 6:29 PM

Date of Loss: 1/1/2021 1:00 AM Date Received: 10/5/2023 9:00 PM Date Inspected: 10/18/2023 10:36 AM Date Entered: 10/8/2023 3:43 PM

Date Est. Completed: 11/11/2023 10:43 AM

Price List: LANORLA1\_JUN22\_FE

Restoration/Service/Remodel

Estimate: 282522\_CO\_1



## **Change Order 1**

The Restore Louisiana Homeowner Assistance Program

For homes being rehabilitated, the HUD Green Building Retrofit Checklist (GBR Checklist) is a Federal construction standard requiring that work performed when receiving Federal funds must meet certain energy efficiency and indoor air quality standards. If the homeowner is under contract or started construction prior to executing the grant agreement, the homeowner is encouraged to use the GBR Checklist to ensure remaining construction is built to energy efficiency and health standards, to the extent feasible. However, if the construction contract is signed or construction activities commence after execution of the grant agreement, all eligible repairs must be performed in line with the GBR Checklist. The Estimated Cost of Repairs (ECR) report for remaining construction was written to the specifications of the GBR Checklist. The GBR Checklist standard does not apply to reconstruction projects.

If the repair value exceeds 80% of the cost of the program estimate to rebuild a home, as determined by the Program, the home will be reconstructed. The Federal government requires that certain energy efficiency standards must be met for reconstructed homes. If a homeowner signs a contract with a contractor to reconstruct the home after signing the grant award, then the new home must be built to ENERGY STAR Certified Home standards.
Homeowner Acceptance of Scope Change
Applicant Number: 282522
Applicant Name: Pearline Foley
I have had the changes in scope of work explained to me, and understand that by signing below, My Grant award will change. The changes may result in a decrease or an increase in my award depending on the changes to which I agree.
I hereby acknowledge and accept that the changes in scope, as described in the line-item review attached to this signature page.  Applicant Signature
Contractor Signature Date/



282522\_CO\_1 Main Level Main Level

Hallway Height: 8'

Missing Wall 2' 1 15/16" X 8' Opens into LIBRARY

Missing Wall 2' 8 13/16" X 8' Opens into DINING\_ROOM

Subroom: Closet (1) Height: 8'

DESCRIPTION QTY UNIT PRICE TOTAL

\*\*\*\*CHANGE ORDER BEING SUBMITTED BY LEMOINE ON 7.3.2024\*\*\*\*

105. R&R Light fixture - Standard grade 1.00 EA @ 66.09 = 66.09

Broken light fixture

Bedroom 1 Height: 8'

Subroom: Closet (1) Height: 8'

DESCRIPTION	QTY	UNIT PRICE	TOTAL
****CHANGE ORDER BEING SUBMITTED BY LEMOINE ON	7.3.2024****		
106. R&R Light fixture - Standard grade	1.00 EA @	66.09 =	66.09
Broken light fixture			
107. R&R Interior door - lauan/mahogany - slab only	1.00 EA @	171.64 =	171.64
wet and swollen door			
110. Door knob/lockset - Detach & reset	1.00 EA @	24.67 =	24.67
install old lock set on new door			
113. Paint door slab only - 2 coats (per side)	1.00 EA @	55.31 =	55.31
Paint new door to match			
114. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA @	47.45 =	47.45
Paint to match new door			

Bathroom 1				Height: 8'
DESCRIPTION		QTY	UNIT PRICE	TOTAL
****CHANGE ORDER BEING SUBMITTED BY LEMOIN	E ON 7.3.2024 ****			
121. Toilet - Detach & reset	1.00	EA@	270.80 =	270.80
To allow for replacement of drywall				
123. Detach & Reset Vanity - Standard grade	2.00	LF @	62.78 =	125.56
to replace drywall				
126. Vanity top - Detach & reset	2.00	LF @	31.63 =	63.26
282522_CO_1			7/2/2024	Page: 3




### **CONTINUED - Bathroom 1**

DESCRIPTION	QTY	UNIT PRICE	TOTAL
To allow for replacement of drywall			
129. P-trap assembly - Detach & reset	1.00 EA @	66.43 =	66.43
To allow for replacement of drywall			
133. Baseboard - 2 1/4"	21.38 LF@	3.08 =	65.85
install on new drywall old base is tile and cannot be reused			
134. Detach & Reset Casing - 2 1/4"	19.00 LF@	2.15 =	40.85
To allow for replacement of drywall			
135. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA @	47.45 =	47.45
paint to match			
136. Mirror - plate glass - Detach & reset	4.00 SF @	6.65 =	26.60
to replace drywall			
139. Heat/AC register - Mechanically attached	1.00 EA @	26.40 =	26.40
Replace missing vent			

### 2nd Level

Bathroom 4			Height: 8'
DESCRIPTION	QTY	UNIT PRICE	TOTAL
****CHANGE ORDER BEING SUBMITTED BY LEMOINE O This bathroom was originally labeled incorrectly as a second clo			
116. Remove Fluorescent light fixture	1.00 EA @	18.51 =	18.51
Broken fixture			
117. Light fixture - Standard grade	1.00 EA @	55.01 =	55.01
replace broken fixture			
118. Seal/prime then paint the ceiling twice (3 coats)	21.22 SF @	1.92 =	40.74
To cover the stain from fluorescent fixture			
119. Remove Outlet	1.00 EA @	6.69 =	6.69
Does not function correctly			
120. Ground fault interrupter (GFI) outlet	1.00 EA @	33.17 =	33.17
Per code and policy guidelines			






# **Change Order 1**

The Restore Louisiana Homeowner Assistance Program

## **Grand Total Areas:**

13,739.48	SF Walls	7,130.67	SF Ceiling	20,870.15	SF Walls and Ceiling
7,194.32	SF Floor	799.37	SY Flooring	1,996.15	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	2,066.66	LF Ceil. Perimeter
7,194.32	Floor Area	7,536.03	Total Area	13,225.65	Interior Wall Area
10,316.61	Exterior Wall Area	983.09	Exterior Perimeter of Walls		
3,233.33	Surface Area	32.33	Number of Squares	463.03	Total Perimeter Length
79.92	Total Ridge Length	0.00	Total Hip Length		





# **Change Order 1**

The Restore Louisiana Homeowner Assistance Program

# **Summary for CO1**

Line Item Total Material Sales Tax		1,318.57 20.31
Replacement Cost Value Net Claim		\$1,338.88 \$1,338.88
	Chris Swider	



## **Recap of Taxes**

Mate	rial Sales Tax (9.2%)	Manuf. Home Tax (9.2%)	Cleaning Mat'l Tax (9.2%)	Fabric Cleaning Tax (9.2%)	Storage Tax (9.2%)	Local Food Tax (4.75%)
Line Items						
	20.31	0.00	0.00	0.00	0.00	0.00
Total						
	20.31	0.00	0.00	0.00	0.00	0.00



# Recap by Room

Estimate: 282522\_CO\_1

**Area: Main Level** 

Area: Ma	ain Level
----------	-----------

Area:	: Main Level		
	Hallway	66.09	5.01%
	Bedroom 1	365.16	27.69%
	Bathroom 1	733.20	55.61%
	Area Subtotal: Main Level	1,164.45	88.31%
Area:	: 2nd Level		
	Bathroom 4	154.12	11.69%
	Area Subtotal: 2nd Level	154.12	11.69%
	Area Subtotal: Main Level	1,318.57	100.00%
Subto	otal of Areas	1,318.57	100.00%
Total	I	1,318.57	100.00%

Page: 8 282522\_CO\_1 7/2/2024



# **Recap by Category**


Items	Total	%
CABINETRY	125.56	9.38%
GENERAL DEMOLITION	58.44	4.36%
DOORS	160.56	11.99%
ELECTRICAL	33.17	2.48%
FINISH CARPENTRY / TRIMWORK	106.70	7.97%
FINISH HARDWARE	24.67	1.84%
HEAT, VENT & AIR CONDITIONING	26.40	1.97%
LIGHT FIXTURES	165.03	12.33%
MARBLE - CULTURED OR NATURAL	63.26	4.72%
MIRRORS & SHOWER DOORS	26.60	1.99%
PLUMBING	337.23	25.19%
PAINTING	190.95	14.26%
Subtotal	1,318.57	98.48%
Material Sales Tax	20.31	1.52%
Total	1,338.88	100.00%



1 Main Level/CO-1 Main Level/Hallway - 166-Hallway Date Taken: 5/2/2024

Taken By: Lemoine

Overview



2 Main Level/CO-1 Main Level/Hallway - 165-Hallway Date Taken: 5/2/2024

Taken By: Lemoine

Light Fixture to be replaced





3 Main Level/CO-1 Main Level/Bedroom 1 - 167-Bedroom

> Date Taken: 5/2/2024 Taken By: Lemoine

Bedroom door to be replaced



4 Main Level/CO-1 Main Level/Bathroom 1 - 171-Bathroom 1

> Date Taken: 5/2/2024 Taken By: Lemoine

Overview





5 Main Level/CO-1 Main Level/Bathroom 1 - 168-Bathroom 1

> Date Taken: 5/2/2024 Taken By: Lemoine

Tile base board to be replaced and vanity to be detached and reset



6 Main Level/CO-1 Main Level/Bathroom 1 - 169-Bathroom 1

> Date Taken: 5/2/2024 Taken By: Lemoine

Mirror, light fixture, and toilet to be

detached and reset





7 Main Level/CO-1 Main Level/Bathroom 1 - 170-Bathroom 1 Date Taken: 5/2/2024

Taken By: Lemoine

Missing vent to be replaced



8 Main Level/CO-1 Level 2/Bathroom 4 - 173-Bathroom 4 Date Taken: 5/2/2024 Taken By: Lemoine

Light fixture to be replaced








9 Main Level/CO-1 Level 2/Bathroom 4 - 172-Bathroom 4 Date Taken: 5/2/2024 Taken By: Lemoine


Out to be replaced with a GFI








Main Level






Roof






2nd Level






CO-1 Main Level

Footprint







Footprint



CO-1 Level 2



Title Please Sign

File name v1lbvvtluqbs04gy6rm75gtk4bff

Document ID ab2d5ff56bbb399262f0d12fe98ab74ad58f11d2

Audit trail date format MM / DD / YYYY

Status • Signed

### This document was requested from app.companycam.com

## **Document History**

O7 / 11 / 2024 Sent for signature to Pearline Foley (vfoley001@yahoo.com)

SENT 19:55:31 UTC from bjohnston@patriotrg.com

IP: 98.173.239.53

O7 / 15 / 2024 Viewed by Pearline Foley (vfoley001@yahoo.com)

VIEWED 20:35:05 UTC IP: 108.203.234.156

SIGNED 20:38:37 UTC IP: 108.203.234.156

7 07 / 15 / 2024 The document has been completed.

20:38:37 UTC