Lemoine Disaster Recovery, L.L.C. 1906 Eraste Landry Rd. Suite 200 Lafayette, LA 70506



#### SUBCONTRACTOR CHANGE ORDER FORM

PROGRAM: LA CDBG

CHANGE ORDER #: 1

DATE:07-30-2024

SUBCONTRACTOR: DSW

PWO ASSIGNMENT NO: 22.6804.45

207433

Becnel, Tanya 168 East 5th Street, Edgard, Louisiana 70049

#### DESCRIPTION OF SCOPE OF WORK CHANGES:

CO1 - BD1 int door, BA2 flooring, Vinyl Plank

PHASE CODE	PHASE DESCRIPTION	AMOUNT
03-1-001	TURNKEY - REHAB SUB	\$1,799.34
03-1-001	BCM Fee	
	Total	\$1,799.34

Contractor: Lemoine Disaster Recovery, L.L.C	Subcontractor: DSW				
(Signature)	(Signature)				
Ben Diebold	Stephen Lott				
(Print Name)	(Print Name)				
8/2/2024	7/30/2024				
(Date)	(Date)				

#### NOT VALID UNTIL SIGNED BY CONTRACTOR AND SUBCONTRACTOR

PLEASE ATTACH THE ENTIRE APPROVED CO ECR SIGNED BY THE HOMEOWNER BEHIND THIS DOCUMENT

	Cha	ange Order 1								
A REAL PROPERTY AND ADDRESS OF AD	The	Restore Louisiana Home	eowner Assistance Program							
Ter ere		Taura Daaral		Calle	(504) 410 5402					
Insu	rea: me:	Tanya Becnel 168 E 5Th St		Cell:	(504) 419-5402					
110	me.	Edgard, LA 70049		E-mail:	tanya4190@icloud.com					
		Eugard, EA 70049								
Claim R	en.:	Kevin Estopinal								
0.000	•p.									
Estima	tor:	Kevin Estopinal								
		-								
Referen	nce:									
Compa	any:	Single Family Home								
Claim Numb	<b>ber:</b> 2	07433	Policy Number: 207433	Туре	of Loss: Hurricane					
Date Contac		12/8/2022 7:38 PM								
Date of L		1/1/2021 12:00 AM	Date Received:							
Date Inspec		12/10/2022 10:38 AM	Date Entered:	12/2/2022 11:28 AM	M					
Date Est. Comple	ted:	12/20/2022 6:55 PM								
Price I	ist:	LANORLA1_JUN22_	FE							
		Restoration/Service/Re								
Estim	ate:	207433_ECR_CO_1								



The Restore Louisiana Homeowner Assistance Program

For homes being rehabilitated, the HUD Green Building Retrofit Checklist (GBR Checklist) is a Federal construction standard requiring that work performed when receiving Federal funds must meet certain energy efficiency and indoor air quality standards. If the homeowner is under contract or started construction prior to executing the grant agreement, the homeowner is encouraged to use the GBR Checklist to ensure remaining construction is built to energy efficiency and health standards, to the extent feasible. However, if the construction contract is signed or construction activities commence after execution of the grant agreement, all eligible repairs must be performed in line with the GBR Checklist. The Estimated Cost of Repairs (ECR) report for remaining construction was written to the specifications of the GBR Checklist. The GBR Checklist standard does not apply to reconstruction projects.

If the repair value exceeds 80% of the cost of the program estimate to rebuild a home, as determined by the Program, the home will be reconstructed. The Federal government requires that certain energy efficiency standards must be met for reconstructed homes. If a homeowner signs a contract with a contractor to reconstruct the home after signing the grant award, then the new home must be built to ENERGY STAR Certified Home standards.

#### Homeowner Acceptance of Scope Change

Applicant Number: 207433 Applicant Name: Tanya Becnel

I have had the changes in scope of work explained to me, and understand that by signing below, My Grant award will change. The changes may result in a decrease or an increase in my award depending on the changes to which I agree.

I hereby acknowledge and accept that the changes in scope, as described in the line-item review attached to this signature page.

Applicant Signature		7/26/2024 Date//
	E8176FFEDBD2409	
Contractor Signature		Date / /
(Solution 1 Only)		Duto/



The Restore Louisiana Homeowner Assistance Program

#### 207433\_ECR\_CO\_1 Main Level

Dining Room				Height: 8'
Missing Wall - Goes to Floor	4' 9'' X 6' 8''	Opens i	nto KITCHEN	
Missing Wall - Goes to Floor	3' 6'' X 6' 8''	Opens i	nto HALLWAY	
Missing Wall - Goes to Floor	4' 1'' X 6' 8''	Opens i	nto LIVING_ROOM	
DESCRIPTION		QTY	UNIT PRICE	TOTAL
****CHANGE ORDER BEING SUBMIT	TTED BY LEMOINE ON 7/13/2	024****		
103. Vinyl floor covering (sheet goods) -	Standard grade	171.58 SF @	-2.91 =	-499.30
Crediting vinyl sheet goods for vinyl plant	k flooring as allowed per policy.			
104. Vinyl plank flooring - Standard grad	e	149.20 SF @	4.87 =	726.60
As allowed per policy.				

Bedroom 1					
DESCRIPTION	QTY	UNIT PRICE	TOTAL		
****CHANGE ORDER BEING SUBMITTED BY LEMOINE ON 7/13/2	2024****				
164. Interior door unit - Standard grade	1.00 EA @	257.11 =	257.11		
Missing door					
165. Paint door slab only - 2 coats (per side)	4.00 EA @	55.31 =	221.24		
To paint interior door					
166. Paint door/window trim & jamb - 2 coats (per side)	4.00 EA @	47.45 =	189.80		
To paint interior door trim					
167. Door knob - interior - Standard grade	1.00 EA @	35.18 =	35.18		
For missing door					

Bedroom 3				Height: 8'
Subroom: Closet (1)				Height: 8'
DESCRIPTION		QTY	UNIT PRICE	TOTAL
****CHANGE ORDER BEING SUBMITTED BY LEMOINE ON 7/13/202	4****			
255. Vinyl floor covering (sheet goods) - Standard grade	204.99	SF @	-2.91 =	-596.52
Crediting vinyl sheet goods for vinyl plank flooring as allowed per policy.				
256. Vinyl plank flooring - Standard grade	178.25	SF@	4.87 =	868.08
As allowed per policy.				



The Restore Louisiana Homeowner Assistance Program

Kitchen				Height: 8'
Missing Wall - Goes to Floor	2' 11" X 6' 8"	<b>Opens into</b>	LAUNDRY_ROOM	
Missing Wall - Goes to Floor	4' 9'' X 6' 8''	<b>Opens into</b>	DINING_ROOM	
Subroom: Pantry (1)				Height: 8'
Missing Wall - Goes to Floor	3' 5'' X 6' 8''	<b>Opens into</b>	KITCHEN	
DESCRIPTION		QTY	UNIT PRICE	TOTAL
****CHANGE ORDER BEING SUBMIT	TED BY LEMOINE ON 7/13	3/2024****		
269. Vinyl floor covering (sheet goods) -	Standard grade	206.58 SF @	-2.91 =	-601.15
Crediting vinyl sheet goods for vinyl plank	t flooring as allowed per polic	у.		
270. Vinyl plank flooring - Standard grad	e	179.64 SF @	4.87 =	874.85
As allowed per policy.				

Bathroom 2				Height: Sloped
DESCRIPTION		QTY	UNIT PRICE	TOTAL
****CHANGE ORDER BEING SUBMITTED BY LEMOINE ON 7/13/2024**	***			
361. Vinyl plank flooring - Standard grade	53.67	SF@	4.87 =	261.37
Replace missing flooring				

### **Grand Total Areas:**

6,894.67	SF Walls	3,552.36	SF Ceiling	10,447.03	SF Walls and Ceiling
3,548.39	SF Floor	394.27	SY Flooring	1,004.00	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	1,079.36	LF Ceil. Perimeter
3,548.39	Floor Area	3,756.00	Total Area	6,894.67	Interior Wall Area
2,972.20	Exterior Wall Area	457.00	Exterior Perimeter of Walls		
1,574.68	Surface Area	15.75	Number of Squares	207.42	Total Perimeter Length
28.62	Total Ridge Length	67.03	Total Hip Length		



The Restore Louisiana Homeowner Assistance Program

# Summary for CO1

Line Item Total	1,737.26
Material Sales Tax	62.08
Replacement Cost Value	\$1,799.34
Net Claim	\$1,799.34

Kevin Estopinal



The Restore Louisiana Homeowner Assistance Program

### **Recap of Taxes**

	Material Sales Tax (9.7%)	Manuf. Home Tax (9.7%)	Cleaning Mat'l Tax (9.7%)	Fabric Cleaning Tax (9.7%)	Storage Tax (9.7%)	Local Food Tax (5.25%)
Line Ite	ems					
	62.08	0.00	0.00	0.00	0.00	0.00
Total						
	62.08	0.00	0.00	0.00	0.00	0.00



The Restore Louisiana Homeowner Assistance Program

### **Recap by Room**

#### Estimate: 207433\_ECR\_CO\_1

Area: Main Level		
Dining Room	227.30	13.08%
Bedroom 1	703.33	40.49%
Bedroom 3	271.56	15.63%
Kitchen	273.70	15.75%
Bathroom 2	261.37	15.04%
Area Subtotal: Main Level	1,737.26	100.00%
Subtotal of Areas	1,737.26	100.00%
Total	1,737.26	100.00%



The Restore Louisiana Homeowner Assistance Program

# **Recap by Category**

Items	Total	%
DOORS	257.11	14.29%
FLOOR COVERING - VINYL	1,033.93	57.46%
FINISH HARDWARE	35.18	1.96%
PAINTING	411.04	22.84%
Subtotal	1,737.26	96.55%
Material Sales Tax	62.08	3.45%
Total	1,799.34	100.00%




1

**Change Order 1** 

The Restore Louisiana Homeowner Assistance Program

CO1 - Main Level/Bedroom 1 -175-Bedroom 1 Date Taken: 6/26/2024 Taken By: Lemoine


Door missing to bedroom 1



2 CO1 - Main Level/Bathroom 2 -176-Bathroom 2 Date Taken: 6/26/2024 Taken By: Lemoine

Missing flooring in bathroom 2






[2] 介

# Main Level

Docusign Envelope ID: 823497FA-FEE6-4D48-8540-7085A9E7FC1E Root



[2] 介

# Roof

7/20/2024

Page: 11





図 介

# Footprint

Page: 12



[2] 介

Page: 13

7/20/2024